




Industrial Barcode Printer

TTP286MT Series

Thermal Transfer • Direct Thermal

Series Models

TTP-286MT/ TTP-384MT



Release Note

Copyright

©2023 TSC Auto ID Technology Co., Ltd.

The copyright in this manual, the software and firmware in the printer described are owned by TSC Auto ID Technology Co., Ltd. All rights reserved.

CG Triumvirate is a trademark of Agfa Corporation. CG Triumvirate Bold Condensed font is under license from the Monotype Corporation. Windows is a registered trademark of Microsoft Corporation.

All other trademarks are the property of their respective owners. Information in this document is subject to change without notice and does not represent a commitment on the part of TSC Auto ID Technology Co. No part of this manual may be reproduced or transmitted in any form or by any means, for any purpose other than the purchaser's personal use, without the expressed written permission of TSC Auto ID Technology Co.

Contents

A2.19 Release Note2

A2.19 Release Note

Category	Description	Model
MENU	Add DIAG GPIO menu for monitoring GPIO card status.	MB240, MB340, MB241 、MB341 、MB641, MH240, MH340, MH640, MH241, MH341, MH641, MH261, MH361, ML240P, ML340P, MX240P, MX340P, MX640P, MX241P, MX341P, MX641P, PEX-1120, PEX-1130, PEX-1160, PEX-1121, PEX-1131, PEX-1161, PEX-1220, PEX-1230, PEX-1260, PEX-1221, PEX-1231, PEX-1261, PEX-2240L, PEX-2340L, PEX-2640L, PEX-2240R, PEX-2340R, PEX-2640R, PEX-2260L, PEX-2360L, PEX-2260R, PEX-2360R
TPH	Add MB41 600 DPI Resolution	MB241 、MB341 、MB641
ETHERNET	Add IPv6 Function	4D520P, 4T520P, 4T530P, DA220, DA320, DH220 、DH320, DH240 、DH340, DL241, MB241 、MB341 、MB641, MH241, MH341, MH641, MH261, MH361, ML241 、ML341, MX241P, MX341P, MX641P, PEX-1121, PEX-1131, PEX-1161, PEX-1221, PEX-1231, PEX-1261, PEX-2240L, PEX-2340L, PEX-2640L, PEX-2240R, PEX-2340R, PEX-2640R, PEX-2260L, PEX-2360L, PEX-2260R, PEX-2360R, TC210, TC310, TE210, TE310, TH220 、TH320, TH240 、TH340, TL241, TL341, TTP286MT, TTP384MT, TX210, TX310, TX610
PRINT SECURE	Add IPv6 PRTSecure Command "Allowed.IP6-b" and "Allowed.IP6" and "Blocked.IP6-b" and "Blocked.IP6"	4D520P, 4T520P, 4T530P, DA220, DA320, DH220 、DH320, DH240 、DH340, DL241, MB241 、MB341 、MB641, MH241, MH341, MH641, MH261, MH361, ML241 、ML341, MX241P, MX341P, MX641P, PEX-1121, PEX-1131, PEX-1161, PEX-1221, PEX-1231, PEX-1261, PEX-2240L, PEX-2340L, PEX-2640L, PEX-2240R, PEX-2340R, PEX-2640R, PEX-2260L, PEX-2360L, PEX-2260R, PEX-2360R, TC210, TC310, TE210, TE310, TH220 、TH320, TH240 、TH340, TL241, TL341, TTP286MT, TTP384MT, TX210, TX310, TX610
WIFI	Add Wi-Fi WPA3 Mode.	DH220 、DH320, DH240 、DH340, MB241 、MB341 、MB641, MH241, MH341, MH641, MH261, MH361, ML241 、ML341, MX241P, MX341P, MX641P, PEX-1121, PEX-1131, PEX-1161, PEX-1221, PEX-1231, PEX-1261, PEX-2240L, PEX-2340L, PEX-2640L, PEX-2240R, PEX-2340R, PEX-2640R, PEX-2260L, PEX-

		2360L, PEX-2260R, PEX-2360R, TC210, TC310, TH220 、TH320, TH240 、TH340, TX210, TX310, TX610
PRINT SECURE	Fix PRTSecure menu not showing for clone when set to default value.	MB241 、MB341 、MB641, MH241, MH341, MH641, MH261, MH361, ML241 、ML341, MX241P, MX341P, MX641P, PEX-1121, PEX-1131, PEX-1161, PEX-1221, PEX-1231, PEX-1261, PEX-2240L, PEX-2340L, PEX-2640L, PEX-2240R, PEX-2340R, PEX-2640R, PEX-2260L, PEX-2360L, PEX-2260R, PEX-2360R, TH220 、TH320, TH240 、TH340, TX210, TX310, TX610
PRINT SECURE	Modify Non-EUR regions should apply EUR regulations when switched to strict mode	4D520P, 4T520P, 4T530P, DA220, DA320, DH220 、DH320, DH240 、DH340, DL241, MB241 、MB341 、MB641, MH241, MH341, MH641, MH261, MH361, ML241 、ML341, MX241P, MX341P, MX641P, PEX-1121, PEX-1131, PEX-1161, PEX-1221, PEX-1231, PEX-1261, PEX-2240L, PEX-2340L, PEX-2640L, PEX-2240R, PEX-2340R, PEX-2640R, PEX-2260L, PEX-2360L, PEX-2260R, PEX-2360R, TC210, TC310, TE210, TE310, TH220 、TH320, TH240 、TH340, TL241, TL341, TTP286MT, TTP384MT, TX210, TX310, TX610
ETHERNET	Add CloudConnect 1.0	DH220 、DH320, DH240 、DH340, MB241 、MB341 、MB641, MH241, MH341, MH641, MH261, MH361, ML241 、ML341, MX241P, MX341P, MX641P, PEX-1121, PEX-1131, PEX-1161, PEX-1221, PEX-1231, PEX-1261, PEX-2240L, PEX-2340L, PEX-2640L, PEX-2240R, PEX-2340R, PEX-2640R, PEX-2260L, PEX-2360L, PEX-2260R, PEX-2360R, TH220 、TH320, TH240 、TH340, TX210, TX310, TX610
PSN	Fix Incorrect mileage conversion when switching between different printhead resolutions.	DH220 、DH320, DH240 、DH340, MB240, MB340, MB241 、MB341 、MB641, MH241, MH341, MH641, ML241 、ML341, MX241P, MX341P, MX641P, PEX-1121, PEX-1131, PEX-1161, PEX-1221, PEX-1231, PEX-1261, PEX-2240L, PEX-2340L, PEX-2640L, PEX-2240R, PEX-2340R, PEX-2640R, PEX-2260L, PEX-2360L, PEX-2260R, PEX-2360R, TH220 、TH320, TH240 、TH340, TX210, TX310, TX610
USB	Fix USB device occasionally not detected.	MH241, MH341, MH641, MX241P, MX341P, MX641P, PEX-1121, PEX-1131, PEX-1161, PEX-1221, PEX-1231, PEX-1261, PEX-2240L, PEX-2340L, PEX-2640L, PEX-2240R, PEX-2340R, PEX-2640R, PEX-2260L, PEX-2360L, PEX-2260R, PEX-2360R

