



Industrial Barcode Printer

MB241 Series

Thermal Transfer • Direct Thermal

Series Models

MB241 / MB241T

MB341 / MB341T



Release Note

Copyright

©2023 TSC Auto ID Technology Co., Ltd.

The copyright in this manual, the software and firmware in the printer described are owned by TSC Auto ID Technology Co., Ltd. All rights reserved.

CG Triumvirate is a trademark of Agfa Corporation. CG Triumvirate Bold Condensed font is under license from the Monotype Corporation. Windows is a registered trademark of Microsoft Corporation.

All other trademarks are the property of their respective owners. Information in this document is subject to change without notice and does not represent a commitment on the part of TSC Auto ID Technology Co. No part of this manual may be reproduced or transmitted in any form or by any means, for any purpose other than the purchaser's personal use, without the expressed written permission of TSC Auto ID Technology Co.

Contents

B1.27.006 Release Note2

B1.27.006 Release Note

RFID

- Issue where RFID-only jobs would print the previous print job
- Allow carriage to be opened during peel calibration step
- Fixed can't upgrade firmware from web after remote panel was opened.
- Crashes when entering RFID menu after reading tags > 64 bytes
- Fix BT UserConfirm mode When connect finished, LED Model LED still blink
- Fix incorrect LCD cursor position in INPUT mode.

