

V 7.08 Summary of Printer Firmware Changes

If you would like to update the firmware V7.08 EZ for the printer, please note that:

1. Your data in the printer's FLASH memory will be cleared out after updating V7.08 EZ from the version which is older than V6.95EZ (not include).
2. If you use USB interface, you will need to install the driver again after updating this firmware from the version which is older than V6.95 EZ (not include).

System

- * Fix the issue for Code16K barcode
- * Disable the line mode power-on utility function
- * Add the Serbian language shown on LCD for TTP-2410M series

TSPL2

- * Fix the issue for Code93 ascii '-' character
- * Modify the SET VERIFIER command
- * Fix the issue that "@" global variable can't be set
- * Fix the issue for LOB() command
- * Add PUTBMP command to support .GRF format
- * Fix the issue for daylight saving time
- * Fix the @MONTH, @DATE, @HOUR, @MINUTE, @SECOND commands to support two-digit format

ZPL2 emulator

- * Fix the issue for Datamatrix ECC200
- * Add MXML command
- * Add ~JE command (exit dump mode)
- * Add ~JR command (power-on reset)
- * Fix the ~DB character code
- * Fix the issue that ~DB command & FontMult Height isn't correct

EPL2 emulator

- * Fix the TD command
- * Fix the issue that code128 decode the FUN1~FUN4 isn't correct
- * Fix the DataMatrix 2D Barcode
- * Ignore it if all the bytes are 0x20